

Message Text

UNCLASSIFIED

PAGE 01 BANGKO 06891 070721Z
ACTION FAA-00

INFO OCT-01 EUR-12 EA-12 ISO-00 EB-08 DOTE-00 /033 W
-----001938 070722Z /15

R 070429Z MAR 78
FM AMEMBASSY BANGKOK
TO SECSTATE WASHDC 1172
INFO AMCONSUL MONTREAL
AMEMBASSY OTTAWA

UNCLAS BANGKOK 6891

E.O. 11652: N/A
TAGS: EAIR, TH
SUBJ: CIVAIR: U.S. TRSB MICROWAVE LANDING SYSTEM

REF: BANGKOK 6675

1. MR. ARDHARN KULLAVANIJAYA, WHO WILL REPRESENT THAILAND AT MONTREAL MLS SESSION APRIL 4-11, CALLED AT EMBASSY MARCH 7 TO DISCUSS PROPOSED VISIT TO MLS SITE AT CROW'S LANDING. ALTHOUGH TRAVEL AND HOTEL RESERVATIONS NOT REPEAT NOT YET CONFIRMED, MR. ARDHARN IS TENTATIVELY PLANNING TO ARRIVE SAN FRANCISCO MARCH 27 AND TO BE AVAILABLE TO VISIT CROW'S LANDING FACILITY MARCH 28. IN ADDITION, INASMUCH AS HE IS IN PROCESS OF INSTALLING WILCOX MARK I/D ILS AT DON MUANG, MR. ARDHARN WOULD ALSO LIKE TO VISIT INSTALLATION, PREFERABLY AT OR NEAR SAN FRANCISCO, WHERE THIS SYSTEM IS OPERATING. PLEASE ADVISE.

2. WITH REGARD ILS EQUIPMENT, MR. ARDHARN WOULD APPRECIATE RECEIVING FOLLOWING FAA HANDBOOKS, WHICH DEPARTMENT IS REQUESTED TO POUCH TO EMBASSY:

FAA HANDBOOK:

- MAINTENANCE OF ILS LOCALIZER EQUIPMENT (WILCOX MARK I/D)
- MAINTENANCE OF ILS GLIDESLOPE EQUIPMENT (WILCOX MARK I/D)

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 BANGKO 06891 070721Z

- MAINTENANCE OF 75 MHZ MARKER FACILITIES (WILCOX MARK I/D)
- MAINTENANCE OF VOR EQUIPMENT (WILCOX 485 A/B)
- MAINTENANCE OF DME EQUIPMENT (WILCOX 496)
- MAINTENANCE OF NDB EQUIPMENT (WILCOX 785E)
- INSTALLATION INSTRUCTION MANUAL FOR NDB, VOR, ILS.

WHITEHOUSE

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: PUBLICATIONS, MICROWAVE EQUIPMENT
Control Number: n/a
Copy: SINGLE
Draft Date: 07 mar 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 jan 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978BANGKO06891
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780101-0898
Format: TEL
From: BANGKOK
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t197803100/aaaadgmf.tel
Line Count: 61
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: f10381b7-c288-dd11-92da-001cc4696bcc
Office: ACTION FAA
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: 78 BANGKOK 6675
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 29 mar 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: N/A
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 3100718
Secure: OPEN
Status: NATIVE
Subject: CIVAIR: U.S. TRSB MICROWAVE LANDING SYSTEM
TAGS: EAIR, APUB, TH
To: STATE
Type: TE
vdkgvwkey: odhc://SAS/SAS.dbo.SAS_Docs/f10381b7-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014